



Förändringar i Åbo trästadsområden

Sanna Kupila











13

UIT-693

picnic



14



100

EUY-975



Kukonvahantie
Kukonvahavägen

Murtomaantie
Terrängvägen

30

LTN 9
046 22947





EKA475

GIR-144

18












Pieteri Valdini katu
Pader Walds gate

1NH976



Julkisivu pihalle




Julkisivu Pietari Valdinkadulle

rea
 , keltainen
 ovienpielet, valkoinen
 a
 en tili
 unainen

aaaleissa ei muutoksia

mat:
 ina GGU, pun. pelti katon sävyyn

m²K
 K



Julkisivu Köydenpunojankadulle



A long, single-story house with a red tiled roof and yellow vertical siding. The house features a dark grey base, multiple windows, and three dormer windows. A white picket fence runs along the side of the property.

A paved road with a white zebra crossing and a grassy verge. The road is situated in front of the house.

A paved road with white dashed lines, situated in front of the grassy verge.

A two-story house with a dark roof and light-colored siding, partially visible on the left side of the image.


A blue and red circular sign with a white diagonal line, indicating a no parking zone, and a yellow square sign with a black border and a black symbol, possibly a speed limit sign.

A white picket fence running along the side of the property.

A white picket fence running along the side of the property.

A large, leafy tree with a white trunk, situated on the right side of the image.





Julkisivu pihalle




Julkisivu takapihalla

- 1 Sokkeli, t.ruskea
- 2 Lautaverhous, keltainen
- 3 Ikkunoiden- ja ovienpielet, valkoinen
- 4 Ovet, v.ruskea
- 5 Katto, punainen tiili
- 6 Kattoikkuna, punainen

Julkisivumateriaaleissa ei muutoksia

*Uudet kattoikkunat:
Velux Lumi-ikkuna GGU, pun. pelti katon sävyyn
koko 78x140
U -vaad 1,0 W/m²K
U-tot. 1,0 W/m²K*



Uusi ikkuna



A long, single-story building with a red-tiled roof and white vertical siding. The building features several windows and two skylights. It is situated at a street intersection.

A paved road with a zebra crossing in the foreground. The road is dark asphalt with white painted stripes. There are shadows cast by trees on the left side of the road.

A large, leafy tree with green foliage and some red flowers, located on the left side of the image.

A large, leafy tree with green foliage, located behind the building on the left side.

A tall, thin tree with green foliage, located behind the building in the center.

A large, leafy tree with green foliage, located behind the building on the right side.

A large, leafy tree with green foliage, located on the right side of the image.

A small, single-story building with a red-tiled roof and light-colored walls, located on the right side of the image.

A tall, silver street lamp with two light heads, located at the intersection.

A tall, silver street lamp with two light heads, located on the right side of the road.

A blue square sign with a white pedestrian symbol, located at the intersection.

A red circular sign with a white center, located at the intersection.

A blue square sign with a white pedestrian symbol, located on the right side of the road.





Port Arthur

















3







Beckholmen




CHJ210









**1940-1950-tals
bostadsområden**



13

LAG-793

















Tack!